

Exohermic Welding

HerWeld Accessories

Standard: NA

HerWeld accessories are necessary tools to make exothermic welding.



| Part Number | Product Description                           |  |  | Unit Weight |
|-------------|-----------------------------------------------|--|--|-------------|
| HEW 46703   | HerWeld Welding Mould Standard Size           |  |  | 1,600       |
| HEW 46704   | HerWeld Welding Mould Large Size              |  |  | 2,200       |
| HEW 46760   | HerWeld Flint Igniter (Mechanical)            |  |  | 0,100       |
| HEW 46767   | HerWeld Flint Igniter (Electronic Controller) |  |  | 0,360       |
| HEW 46454   | HerWeld Controller Fuse                       |  |  | 0,002       |
| HEW 46845   | HerWeld Scraper                               |  |  | 0,080       |
| HEW 46770   | HerWeld Mould Seal                            |  |  | 1,000       |
| HEW 46772   | HerWeld Anticorrossion Tape                   |  |  | 1,000       |
| HEW 46803   | HerWeld Mould Handle                          |  |  | 1,130       |
| HEW 46880   | HerWeld Brush for Conductor                   |  |  | 0,100       |
| HEW 46890   | HerWeld Brush for Mould                       |  |  | 0,020       |
|             |                                               |  |  |             |
|             |                                               |  |  |             |
|             |                                               |  |  |             |
|             |                                               |  |  |             |
|             |                                               |  |  |             |